

# BARN REGISTER FORM

File Code #



Construction Date: **late 1940s**  
 Builder's Name (if available):

## Idaho Heritage Barns Preservation Idaho



<b>Farm Name:</b> Mack & Rita Miller Farm	<b>Property Location:</b> Address: East end of Roseberry Rd. City: Donnelly State: Idaho Zip: 83615 <b>County:</b> Valley
<b>Historic</b> (or other names associated with farm): Brad Barker barn	<b>Legal Description:</b> Township: N or S Range: W or E Section: ¼ Section: NW,NE,SW,SE Latitude: Longitude:
<b>Property Owner:</b> Name: Mack & Rita Miller Address: Box 297 City: Donnelly State: Idaho Zip: 83611 Phone: 469-9152 Email: Mackrita@msn.com	<b>Directions:</b>

Barn	Roof Shape	Roof Covering	Floor Plan	Siding	Foundation/Frame	Features
<b>Condition:</b> <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Altered <input type="checkbox"/> Ruins  <b>Historic Uses:</b> <input type="checkbox"/> Cow Barn <input type="checkbox"/> Horse Barn <input type="checkbox"/> Dairy Barn <input type="checkbox"/> Hay <input checked="" type="checkbox"/> Other  <b>Current Use:</b> <input type="checkbox"/> Agriculture <input type="checkbox"/> Vacant <input checked="" type="checkbox"/> Storage <input type="checkbox"/> Other	<input type="checkbox"/> Shed <input checked="" type="checkbox"/> Gable <input type="checkbox"/> Hip <input type="checkbox"/> Dutch Gable <input type="checkbox"/> Four Square <input type="checkbox"/> Monitor <input type="checkbox"/> Salt Box <input type="checkbox"/> Broken Gable <input type="checkbox"/> Half Monitor <input type="checkbox"/> Gambrel <input type="checkbox"/> Vault <input type="checkbox"/> Gothic Arch <input type="checkbox"/> Round	<input type="checkbox"/> Asphalt <input type="checkbox"/> Asphalt Roll <input checked="" type="checkbox"/> Metal <input checked="" type="checkbox"/> Wood Shingles <input type="checkbox"/> Wood Boards <input type="checkbox"/> Other	<input type="checkbox"/> Square <input checked="" type="checkbox"/> Rectangular <input type="checkbox"/> Round <input type="checkbox"/> Irregular <input type="checkbox"/> L- Shape <input type="checkbox"/> T- Shape  <b>Floor Size:</b> Length: 54'-2" Width: 56'-4" Height: 36'	<input type="checkbox"/> Metal <input type="checkbox"/> Wood-Horizontal <input type="checkbox"/> Wood-Board/ Batten <input type="checkbox"/> Wood Vertical <input type="checkbox"/> Concrete <input type="checkbox"/> Brick <input type="checkbox"/> Stone <input type="checkbox"/> Asbestos <input type="checkbox"/> Other	<input type="checkbox"/> Concrete Block <input checked="" type="checkbox"/> Concrete <input type="checkbox"/> Stone <input type="checkbox"/> Brick <input type="checkbox"/> Wood <input type="checkbox"/> None <input type="checkbox"/> Other  <b>Framing:</b> <input type="checkbox"/> Round Logs <input type="checkbox"/> Hand Hewn <input checked="" type="checkbox"/> Dimensional lumber <input type="checkbox"/> Other	<input type="checkbox"/> Not painted <input checked="" type="checkbox"/> Painted Color: Brown <input type="checkbox"/> Cupola <input type="checkbox"/> Hay hood <input type="checkbox"/> Ventilator <input type="checkbox"/> Weather Vane <input type="checkbox"/> Lightning Rod <input type="checkbox"/> Silo <input type="checkbox"/> Milk Shed <input type="checkbox"/> Other

**Additional Information:** Expand on the history of the barn or property such as owners, architect, stories, etc. Use additional pages if necessary:

New doors and windows were installed in the early 90s in the original openings. Barn features a widows peak.

**Please submit with this form:** Current photos of the Barn. **Exterior:** setting and view of all four sides. **Interior:** four sides, roof framing and unusual details. Submit in high resolution prints on photo paper. Copies of historic photos may also be submitted. Include a Google map or drawing of the location of farmstead buildings in relation to the barn.

**Information Contact:** \_\_\_\_\_ **Recorded by:** \_\_\_\_\_ **Date Submitted:** \_\_\_\_\_ **Affiliation:** \_\_\_\_\_ **Property Accessed? Y or N** \_\_\_\_\_

**BARN REGISTER FORM – P 2**

**OTHER FARMSTEAD BUILDINGS**

BUILDINGS & CONDITION:	BUILT DATE & BUILDER	ROOF STYLE & COVERING	SIDING & FOUNDATION	FLOOR PLAN AND OTHER FEATURES (Square, L-Shape, Rectangular, Style, Color, Trim, etc..)
<b>DWELLING:</b> <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Altered <input type="checkbox"/> Ruins <input type="checkbox"/> N/A	Date <b>1999</b>  Builder	Roof Style <b>Gable</b>  Covering <b>Tin</b>	Siding <b>Log</b>  Foundation <b>Cement</b>	
<b>GARAGE:</b> <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Altered <input type="checkbox"/> Ruins <input type="checkbox"/> N/A	Date  Builder	Roof Style  Covering	Siding  Foundation	
<b>CHICKEN COOP:</b> <input checked="" type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input checked="" type="checkbox"/> Altered <input type="checkbox"/> Ruins <input type="checkbox"/> N/A	Date <b>?</b>  Builder	Roof Style  Covering <b>Tin</b>	Siding  Foundation	
<b>MACHINE SHED or BLACKSMITH:</b> <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Altered <input type="checkbox"/> Ruins <input type="checkbox"/> N/A	Date  Builder	Roof Style  Covering	Siding  Foundation	
<b>SHED:</b> <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Altered <input type="checkbox"/> Ruins <input type="checkbox"/> N/A	Date  Builder	Roof Style  Covering	Siding  Foundation	
<b>OTHER: Teacherage</b> <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Altered <input type="checkbox"/> Ruins <input type="checkbox"/> N/A	Date  Builder	Roof Style  Covering	Siding  Foundation	
<b>OTHER: Sauna</b> <input type="checkbox"/> Good <input type="checkbox"/> Fair <input type="checkbox"/> Poor <input type="checkbox"/> Altered <input type="checkbox"/> Ruins <input type="checkbox"/> N/A	Date <b>2005</b>  Builder	Roof Style <b>Gable</b>  Covering <b>Tin</b>	Siding  Foundation <b>Cement</b>	

Miller aquired in 1989.

Rita Barker inherited from her mother (who was a Barker.) Brod and Tilda were Rita's parents. Rita's mother was a Norton.

Lived at Sugarloaf, when Reservoir built her mother moved to near Donnelly.

She married Barker and they built in Roseberry.

Southern boards were replaced in 90

East side west, north all original boards.

He said they cut lumber for the barn at the place, sawmill at Pottengers.

The boards-pine; shingles – tamarack.

Structure on south side – a ring – to tie the rope to to suspend themselves while they were painting.

Chicken coop is a chopped haywagon, was Rita's Uncles, Henry Norton, who lived 3 miles no of Donnelly on Hwy 55.

Original house a trailer. Sauna built only 5 years ago. Newer house 1999.

Barn foundation handpoured cement. Footings on outside wall are L fitting. Why east side barn has slipped – the L footings don't hold as well as the T. No footings on end walls, just on the sides.

No exterior eve boards on the ends.

Widows peak on N end holds Jackson Fork. Flying Gable or eave.

They leased to Jim Little, brother of Brad. To raise calves.

Notes – Miller Barn 102611-1

Discussion with Mack Miller -

The Brod Barker Barn owned by Mac and Rita Miller.

End of East Roseberry rd as turns into Gold Fork Rd.

Built with Ray Eld's help. (Elva was Brod Barker's real name.)

Barn built on site, owners were going to live at it, but they never did.

School was hauled into the site, then it was moved.

The barn was built around 1940 or even into late 40s.

Built for hay, never finished.

Part of Pottenger place next to Prince Pottenger homestead.

Barker got from Pottenger.

The roof was replaced 3-4 years ago.

Original shingles still in place.

Never sided, just boards.

Since they didn't live here, they never finished the barn.

Newer doors and window openings built by Don Forsyth early 90s. Window holes are original.

The roof was sagging, they did something with it.

Barn always used for hay, now storage.

Rope track and hoist in place for hay.

Gravel floor.

Where the roof humped the roofer took the shingles off so the roof lay flat.

Built some interior storage areas.

PHOTO INVENTORY OF LONG VALLEY BARN

Date 9/4/95 Map # ID = Barker/Miller

Location almost 2 miles E. Roseberry off end of E. Roseberry Rd T16N R4E S7+8

Present owner and mailing address Mae + Rita Miller (Tilda Barker = Rita's mother)

History of barn - date built, whose ranch or farm, uses of barn, etc.

Built by Brod Barker in 1930's + split shingles = neighbors (Ray Eld helped) - stored hay. had been homesteaded by Pottengers who sold to Barkers in 1904

Type of barn architecture - (Gothic, gable, gambrel, modified, Finn)

75' x 50' wide

Present condition of barn good - stained brown cement foundation

Present use of barn storage



Nelle's photos = B+W of wagon - Iva Pottenger 3/24/08 9.15.03 barn Wm Barker 6/6/06

Photo identification: Roll # 5 Barn # (on that roll) 4

T. 16 N. R. 4 E Sec 7+8  
Rita's place + negatives (3)  
wagon - Iva Pottenger 3/24/08  
9.15.03  
Barn - Wm Barker 6/6/06

ication purposes: brown + shingles

16.4.8-1a - Barn

16.4.7-1a - Wagon  
1b "

16.4-7-8  
3 B+W prints  
3 negs.

16.4.7-1a  
1b

16.4.8-1a  
W negs

Barn # \_\_\_\_\_)

